


- LEGEND**
- storm sewer
  - suspected utility
  - suspected utility, amount #
  - stacked vertically
  - characteristics fence
  - GPR profile start (S) and stop (E)
  - metal detector anomaly
  - tunnel sections found with GPR
  - locked tunnel section
  - tunnel section, with VT-150
  - parallel crawler
  - collapsed tunnel
  - exploratory drilling hole
  - catch basin
  - parking lot lamp
  - manhole cover
  - utility pole
  - aboveground storage tank
  - surface soil depression
  - current building
  - electrical conduit bank

**Freeland Engineering, PC**  
rfreeland@freelandengineeringpc.com  
10814 Courthouse Road  
Fredericksburg, Virginia 22408  
Phone: 540.898.3092  
Fax: 877.658.7735  
www.freelandengineeringpc.com



**NAEVA** CERTIFIED, INC.  
2014, Phase 201, Code 100  
Cognate, NY 10800  
940286-1927 FAX

Prepared for:  
**APEX**  
8854 Rixlew Lane  
Manassas, Virginia

Plate 2: Tunnel Prioritization of Workhouse Arts Center  
9601 Ox Road, Lorton, VA

Client	Apex Companies, LLC	Date of Work	March 16 - 27, 2015
Project No.	C1503161L	Map By	Daniel Lefini
ALL UNDERGROUND FACILITIES MAY NOT BE DETECTED ON THIS MAP			